

Shamir Autograph Plus™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking
Hard Resin	1.498	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Clear	14, 16, 18	15 S +X 250
Transitions®	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	TR S +X 250
Transitions® XTRActive™	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray	14, 16, 18	X5 S +X 250
Polarized	1.498	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ S +X 250
Drivewear®	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Drivewear®	14, 16, 18	DW S +X 250
DLC™ (Trivex)	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	TX S +X 250
DLC™ (Trivex) Transitions®	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	TTX S +X 250
DLC™ (Trivex) Polarized	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	PTX S +X 250
1.56	1.56	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	56 S +X 250
Polycarbonate	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Clear	14, 16, 18	PC S +X 250
Polycarbonate Transitions®	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray & Brown	14, 16, 18	PT S +X 250

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

Shamir Autograph Plus™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking
Polycarbonate Transitions® XTRActive™	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray	14, 16, 18	PX Ⓢ +X 250
Polycarbonate Polarized	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray & Brown	14, 16, 18	PPZ Ⓢ +X 250
Polycarbonate Drivewear®	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Drivewear®	14, 16, 18	PD Ⓢ +X 250
Superlite™ 1.6	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	16 Ⓢ +X 250
Superlite 1.6 Transitions®	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	T6 Ⓢ +X 250
Superlite 1.6 Transitions® XTRActive™	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray	14, 16, 18	X6 Ⓢ +X 250
Superlite 1.6 Polarized	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ6 Ⓢ +X 250
Superlite 1.67	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14, 16, 18	67 Ⓢ +X 250
Superlite 1.67 Transitions®	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	T67 Ⓢ +X 250
Superlite 1.67 Transitions® XTRActive™	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray	14, 16, 18	X67 Ⓢ +X 250
Superlite 1.67 Polarized	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ67 Ⓢ +X 250
Superlite 1.74	1.74	-18.75 to +14.75	0.5, 1.5, 2.5, 3.5, 4.75, 6, 7.25, 8.25, 9, 9.75, 10.5, 11.25, 12	0.75 to 3.50	Clear	14, 16, 18	74 Ⓢ +X 250

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

Shamir Autograph Plus™ Mineral

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking
1.60 White	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	G16 S +X S 250
1.60 Photochromic Gray	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray	14, 16, 18	GP16 S +X S 250
1.60 Photochromic Brown	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Brown	14, 16, 18	GP16 S +X S 250

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®